

INFORMAÇÕES SOBRE A UTILIZAÇÃO SEGURA DE SVHC

INFORMAÇÕES RELATIVAS AO ARTIGO 33.º DO REGULAMENTO REACH SOBRE SUBSTÂNCIAS QUE SUSCITAM ELEVADA PREOCUPAÇÃO

Estimado(a) Cliente,

O Artigo 33.º, parágrafo 1 do Regulamento REACH (Regulamento CE n.º 1907/2006) destina-se a possibilitar que os clientes de produtos fornecidos tomem medidas de gestão de riscos adequadas, que poderão ser necessárias devido à presença de Substâncias que Suscitam Elevada Preocupação (SVHC) nos artigos, indicadas na Lista de Substâncias Candidatas a Autorização atual, no sentido de garantir uma utilização segura.

De um modo geral, a FORD apoia os objetivos subjacentes do Regulamento REACH e especificamente o Artigo 33.º, parágrafo 1, que são compatíveis com o nosso próprio compromisso em promover o fabrico, manuseamento e a utilização responsáveis dos nossos produtos.

Identificação de SVHC

Tanto quanto é do nosso conhecimento, com base nas informações recebidas da nossa cadeia de fornecimento e dos nossos dados de produtos, as SVHC presentes nos componentes dos artigos em quantidades superiores a 0,1% p/p são as indicadas na respetiva "Lista de SVHC" para a peça ou veículo específico.

Informações específicas sobre a utilização segura de artigos que contêm SVHC

Se aplicável, as informações específicas sobre a utilização segura de artigos que contêm SVHC será adicionada à respetiva "Lista de SVHC" da peça ou veículo específico.

Informações gerais sobre a utilização segura de artigos

Todos os veículos FORD são fornecidos com um manual do proprietário, que inclui informações sobre a utilização segura para os proprietários ou condutores dos veículos. As informações FORD sobre reparação e revisão dos veículos e das peças genuínas também incluem informações sobre a utilização segura para o pessoal de serviço.

Quando as SVHC indicadas na "Lista de SVHC" da respetiva peça ou veículo estiverem presentes, são incorporadas de forma a minimizar a eventual exposição aos clientes. O perigo para os seres humanos ou para o ambiente pode ser excluído, desde que o veículo e as respetivas peças sejam utilizados conforme previsto, e as reparações, revisões e manutenção sejam realizadas de acordo com as instruções técnicas para essas atividades e boas práticas da indústria.

Os veículos em fim de vida poderão ser eliminados de forma legal na União Europeia apenas em Instalações de Tratamento Autorizadas (ATF). As peças dos veículos devem ser eliminadas de acordo com as leis locais aplicáveis e orientações das autoridades locais.

Modelo: Ford Courier

Lista de SVHC com base na Lista Candidata da ECHA em 1 de julho de 2020

Informações específicas sobre a utilização segura de artigos que contêm SVHC

Não são necessárias informações específicas sobre a utilização segura. Devem ser cumpridas as informações gerais sobre a utilização segura de artigos.

Commodity	REACH SVHCs
A/C Compressor	2-Ethoxyethanol110-80-5
	Lead7439-92-1
A/C Lines, Receiver Drier and Accumulator	Lead7439-92-1
ABS/ESC Module	Imidazolidine-2-thione96-45-7
	Lead7439-92-1
Accessories	1,2-Dimethoxyethane110-71-4
	Hexahydromethylphthalic-anhydride25550-51-0
	Lead7439-92-1
Active and Air Suspension	4-Nonylphenol, branched84852-15-3
	Boric acid10043-35-3
	Lead7439-92-1
Air Bag Module- Pass Side	Refractory ceramic fibres142844-00-6
AIS - Air Cleaner and Low Pressure Ducts	Lead7439-92-1
	Lead-monoxide1317-36-8
AIS - High Pressure Ducts	Imidazolidine-2-thione96-45-7
	Lead7439-92-1
Alternator	4,4'-Isopropylidenediphenol80-05-7
	Lead7439-92-1
Antenna	Lead7439-92-1
Audio and Navigation Head Units	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene13560-89-9
	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
	Lead-titanium-trioxide12060-00-3
Battery	Lead7439-92-1
Body Structure - Decklid/Liftgate (incl Hinge/Supt)	Lead7439-92-1

Body Structure - Floor Pan - Front Floor and Side Sill	Diboron-trioxide1303-86-2
	Lead7439-92-1
Brake - Parking	2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol3864-99-1
	Lead7439-92-1
Brake Tubes and Hoses	Lead7439-92-1
Brakes - Caliper & Anchor Brkt Assy (Front, Rear)	Lead7439-92-1
Brakes - Drum (Front/Rear)	Lead7439-92-1
Bulk Materials (PMT100)	1-Methyl-2-pyrrolidone872-50-4
CHMSL	Diboron-trioxide1303-86-2
EDS Wiring Assembly & Components	Lead7439-92-1
EGR System (Gas/Diesel)	Lead7439-92-1
Electro/Mechanical Devices	Lead7439-92-1
Electro/Mechanical Devices - Reception	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol25973-55-1
	Lead7439-92-1
Electro/Mechanical Devices - Security	Lead(II,IV)-oxide1314-41-6
Electronic Modules - Displays	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
Electronic Modules - Power Sliding Door	Lead7439-92-1
Electronic Modules - SYNC	2-Methylimidazole693-98-1
	Lead-monoxide1317-36-8
Engine Covers and Badges	Lead7439-92-1
Engine Sealing (Including head gaskets)	Lead7439-92-1
Evaporator and Blower Assembly (HVAC Module)	1,2-Benzenedicarboxylic acid, di-C6-8-branched alkyl esters, C7-rich71888-89-6
	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
	Lead-titanium-trioxide12060-00-3
FEAD	Lead7439-92-1
Fixed Glass	Lead7439-92-1
Front / Rear Door Trim	C,C'-azodi(formamide)123-77-3
	Octamethylcyclotetrasiloxane556-67-2
Fuel Delivery Module	Lead7439-92-1
Fuel Filler Pipes	Imidazolidine-2-thione96-45-7
Fuel Injection	Imidazolidine-2-thione96-45-7
	Lead7439-92-1
Fuel Lines	Lead7439-92-1
Fuel Tanks	Decamethylcyclopentasiloxane541-02-6
	Imidazolidine-2-thione96-45-7
	Lead7439-92-1
	Lead-monoxide1317-36-8
Headlamp / Side Marker	Lead7439-92-1
Instrument Cluster	Diboron-trioxide1303-86-2
	Lead titanium zirconium oxide12626-81-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
Interior Lighting	Lead7439-92-1

IP Finish Panels/Registers	Boric acid10043-35-3
Latches - Hood, Decklid and Liftgate Latches	Lead7439-92-1
	Nonoxinol9016-45-9
Latches - Side Door/Latch Mini Module	Lead7439-92-1
	Nonoxinol9016-45-9
Locks	Hexahydromethylphthalic-anhydride25550-51-0
	Lead7439-92-1
Luggage and Interior Cargo Management/Covers	Lead7439-92-1
Park Assist	Lead titanium zirconium oxide12626-81-2
	Lead-monoxide1317-36-8
PATS Transceiver	Lead titanium zirconium oxide12626-81-2
Pedal Box	Lead7439-92-1
Plastic Bumpers and Fascias	Lead titanium zirconium oxide12626-81-2
	Lead-monoxide1317-36-8
Powertrain Control Module (PCM/EEC/ ECM)	Lead7439-92-1
PT Mounts	Lead7439-92-1
PT Sensors	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
	Octamethylcyclotetrasiloxane556-67-2
Rain and Daylight Sensor	Lead7439-92-1
Restraint Electronics	Lead7439-92-1
Retainer Plate Spare Wheel	Lead7439-92-1
Sealing - Door Dynamic Seals	2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol3864-99-1
Seat Belts (Front and Rear)	Lead7439-92-1
Seats - JIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one71868-10-5
	Decamethylcyclopentasiloxane541-02-6
	Lead7439-92-1
	Octamethylcyclotetrasiloxane556-67-2
Shifter Cables/Brackets - Auto	Lead7439-92-1
Shock Absorbers	Lead7439-92-1
Side Air Bag (SAB) and Curtain Air Bag (CAB)	Lead7439-92-1
Sliding Door Mechanism	Lead7439-92-1
Spare Wheel Winch	Lead7439-92-1
Speakers / Tweeters	Imidazolidine-2-thione96-45-7
Stabilizer Bar (Front, Rear -- Solid/Tubular)	2-Methylimidazole693-98-1
	4,4'-Isopropylidenediphenol80-05-7
Steering Column	Lead titanium zirconium oxide12626-81-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
Steering Gear and Linkage	Lead7439-92-1
Suspension Link Components	Lead7439-92-1
Switches - Headlamp. Window & Door	Lead7439-92-1
	Lead-monoxide1317-36-8
Switches - Steering Column	Lead7439-92-1
	Octamethylcyclotetrasiloxane556-67-2

Taillamp / Redundant - xEV - Traction Battery (as Shipped)	Nonoxinol9016-45-9
Temperature Sensors - Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione2451-62-9
	Hexahydromethylphthalic-anhydride25550-51-0
Tires	Lead7439-92-1
TMK and Tools	Lead7439-92-1
TPMS	1,2-Dimethoxyethane110-71-4
	1,3-Propanesultone1120-71-4
	Lead7439-92-1
Transmission - Manual	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate15571-58-1
	Lead7439-92-1
Window Regulator	Lead7439-92-1
Wiper Assembly (Rear, Front) & Washer System	Lead7439-92-1